
“Knock Knock Knock… Housekeeping ”
the ins and outs
of hotel

Hotel Rooms are a Sanctuary

At Least, They're Supposed To

A Place to Curl Up In Bed And D

Or Do Other Things

You Don’t Want This to



So Let's Talk About Room Doors First

Barry & Han – Under Door

The Solution – Always Know Where Your Towel Is

The Solution – Always Know Where Your Towel Is

Douglas Adams…

now an Honorary TOOOL Mmeber

Some People Want Extra Security

Some People Fail at Extra Security

- Attack with a Reach-Around
- Attack with a Rubber

A Different Type of Door

D

Sec

A Different Type of Fail

- Attack with a Slap Tool
- Attack with a Maid Sign

Harder to do at Hotel Penn...

D

“Statler Servidoor”

first at Boston Park Plaza

Modern Hotel Doors Often *Do*[D]

Peepholes are *Supposed* to be for Looking *Out*

Security Consultants Have

One Last Bit of Peephole Fun D

One Last Bit of Peephole Fun

Let’s Say You Choose to Leave

You May Take an Elevator

Time to Stop all the Lies

Floor Lockout

Floor Lockout

Access Panels

Who Left That Open?



What Have We Here?

Dios Mío! Es La Migra!

Another Panel

Yet Another Panel

Some Potential for Confusion



Fire Service Mode

Fire Service Mode



Monthly Elevator Fire Service Test Log

INSTRUCTIONS:

ASME A17.1 Rule 1206.7 states the following; "All elevators provided with firefighters' service shall be subjected monthly to Phase I recall and a minimum of one-floor operation on Phase II to assure the system is maintained in proper operating order. A written record of findings on the operation shall be made and kept on the premises of said operation." Either qualified building personnel or a qualified elevator service company may conduct this monthly test. Post this log in the elevator machine room or in a readily accessible location in the building.

Year 2009

Month	Date Tested	Tested By:	Phase I	Phase II
JAN			☐	☐
FEB			☐	☐
MARCH			☐	☐
APRIL			☐	☐
MAY			☐	☐
JUNE			☐	☐
JULY			☐	☐
AUG			☐	☐
SEPT			☐	☐
OCT			☐	☐
NOV			☐	☐
DEC			☐	☐

Fire Service Keys

Fire Service Keys

Sometimes Keys Do Strange Things

Hoist Equipment



Keys in a Cabinet... One Op



Heh, Such a Thing as Too Ma

More Keys Means More Access

Lots of Noise Behind a Grill

A Closer Look

Cell Tower Equipment

Another Service Log



Date	Technician	Reason on Site
6-25	Wachal	Replaced one of two Bad Rectifiers
6-29	Wachal	Replaced the other Rectifier
7-16-04	Wachal	Rectifier pwr 3 sector 3 carrier Trouble
7-26-04	Wachal	Replaced Grill on entry door
7-26-04	Wachal	365 pwr
7-27-	Wachal	Rectifiers + Shelf need Replaced
8-17	Wachal	Site
8-27	Wachal	T-1 2 Bad - degraded No Trouble found The problem ended up at the BSC in the Switch
9-2	Wachal	added Expansion Rectifiers
9-16	Wachal	Installed Cem48 Slot 10 pwr RF
9-20	Wachal	F-2, F-3 Low to No Pwr Cables Tight Fan filter dirty Cleaned Software on F1
10/01	Wachal	NT-90 Complete
10/04	Wachal	PM's - Added 2 more T-1's
12/04	Wachal	EVDO - @ Nortel
2005		
1-05	Wachal	Install new EQuip for F-3 VOICE
3-2-05	Wachal	Installed new 12 pr T-1 Cable plus 3rd VOICE T-1
5-1-05	Wachal	Removed 48 slot 1 Added 64, added T-1 to Slot 12
8-11-05	Wachal	PM Failure Replace 2 Binds
2006		
3/10/06	Wachal	PM's 180 Room Very Dirty due to Asbestos Crew

PM=Preventive Maint., EM=Emergency Maint., OM=Other Maint.

Another Service Log



Another Service Log



Let’s Get Back To The Room

D

Keycard Access

Disable the Card Reader

We'll Revisit This Later, Too

D

BTW... Does This Math Add Up?

We Don’t Think So



Pin Matrix Room Keys

Pin Matrix Lock



Programmed With a Control

Control Card “A” Installed



Control Card Can “Wiggle”



Pass Card “A” Being Used



Change to Control Card “B”



Understanding the Pin Matrix D



Key Pins



Ball Bearings On Top

D



Pin Matrix Room Keys



This Control Card Would Never Work



At Least Need to Depress Control Pins



At Least Need to Depress Contro



Very Punched Control Card

D



All Ball Bearings Free To Move



A Solid Pass Key Would be Needed



The Solid Pass Key Pushes All D

The Sta



Imagine The Reverse... A Solid

Contro



All Pin Stacks are now Correct



This Pass Card Would be Needed



Ventilated Pass Card Works



A More Typical Control Card



These Stacks are In Position



These Stacks are In Position



These Balls Shouldn't Move Furthe



So… This Would be the Corres



These Stacks Were Already In Position



Only These Ball Bearings Should



Control-Card Based Attacks



Dimpled Control-Card



Ball Bearings Can Sit Lower



“Cookie Tray” Control Card



Ball Bearings Can Sit Lower

D



Pass Key “A” Can Work



Pass Key “B” Can Work



Decoding and Picking Attacks?

Consider This Ball Bearing



Very Springy



Consider This Ball Bearing



Not Nearly as Springy



You May Have Guessed... No

D

Easy Master Keying



No Master Keying Means

Override Keys

Override Lock... Sometimes

D

Hi

Override Lock... Sometimes



Override Lock... Sometimes

D



Override Lock... Sometimes

Magnetic Locks Also Feature D

Magnetic Hotel Keys

Magnetic Hotel Keys

Magnetic Hotel Keys

start bit	site code	room number	key number	“magic” number	expire date	expire time	end bit	check sum
;0000 00	0420	0069	01	0016	20100 720	1200	999	CRC

Magnetic Hotel Keys

start bit	site code	room number	key number	“magic” number	expire date	expire time	end bit	check sum
;000000	0420	0069	01	0016	20100720	1200	999	CRC
;000000	0420	0069	02	0016	20100720	1200	999	CRC

Magnetic Hotel Keys

start bit	site code	room number	key number	“magic” number	expire date	expire time	end bit	check sum
;0000 00	0420	0069	01	0016	20100 720	1200	999	CRC
;0000 00	0420	0069	02	0016	20100 720	1200	999	CRC

Magnetic Hotel Keys

start bit	site code	room number	key number	“magic” number	expire date	expire time	end bit	check sum
;000000	0420	0069	01	0016	20100720	1200	999	CRC
;000000	0420	0069	02	0016	20100720	1200	999	CRC

(last 100 “magic” numbers stored)

Special Hotel Keys

start bit	site code	room number	key number	“magic” number	expire date	expire time	end bit	check sum
;000000	0420	0000	01	0000	20100820	1200	999	CRC

Special Hotel Keys

start bit	site code	room number	key number	“magic” number	expire date	expire time	end bit	check sum
;000000	0420	0000	01	0000	20100820	1200	999	CRC

Special Hotel Keys



Special Hotel Keys

Special Thanks...

Major

Malfunction

Über Hacker

Extraordinaire

From The U.K.

- Yet Loves Firearms
- Not a Nanny-State-Loving Nancy

Come Visit the Lockpick

Thank You Very Much!

Questions?

http://toool.us

http://toool.nl

Thank you to Barry, Han, Major Malfunction, The 2600 Staff, The